Appendix 1

Devolved Community Council Funded Schemes

Community Council : Dulwich

Date: 20 October 2011

Under spend from previous years
£64,257.24

Allocation for FY 2012/13
£100,000

Total available for 2012/13
£164,257.24

Officer Recommendations – 2012/13

Candidate Road	Ward	Identified defects	Suggested treatment	Estimated Cost
Asbourne Grove	East Dulwich	Carriageway : Areas local to sinusoidal speed	Carriageway: Plane off and resurface (40mm) sections	£53,000
		humps have recently been resurfaced ; areas in	between humps. (NB: Might be more viable to remove	
		between have failing trench reinstatements and	speed humps > resurface > reinstate humps);	
	East Dulwich	some surface degradation Carriageway: Areas local to sinusoidal speed	reinstatement of road marking. Carriageway: Plane off and resurface (40mm) sections	£36,300
Chestement Grove	East Duiwich	humps have recently been resurfaced ; areas in	between humps. (NB: Might be more viable to remove	230,300
		between have failing trench reinstatements and	speed humps > resurface > reinstate humps);	
		some surface degradation	reinstatement of road marking.	
College Rd	College	Carriageway : Subsiding trench reinstatements ;	Carriageway: Plane off and resurfacing 40-100mm plus	£64,000
	0	local depressions suggesting sub base / grade	some full depth reconstruction in places; reinstatement of	
		failing; repeated patching in various states of	traffic calming and road marking.	
		degradation; rutting ; longitudinal and transverse		
		cracking		
Seeley Drive	College	Carriageway : Local deformations; potholes;	Carriageway: Plane off and 40mm resurfacing;	£38,400
	0 "	Irregular cracking ;	reinstatement of 2 speed humps and road marking.	007 000
Colby Rd	College	Carriageway: Previous patch repairs failing;	Carriageway: Plane off and resurface. Plane off and	£27,000
		kerbstones dislodged near some trees; severe longitudinal failure. (NB : Access to Colby Rd	resurface (40mm) near intersection with Dulwich Wood Avenue due to low existing kerb upstand; reinstatement of	
		Nursery needs to be considered)	road marking.	
			road manang.	
		Footway: Uneven northern footway approx 70m	Footway : Relay with flexible surfacing and roll over	£5,000
		long with extensive trenching and patching near	sections near proud tree roots	
		intersection with Dulwich Wood Avenue; some		
		cracking due to tree roots		
Roseway	Village	Carriageway: Local depressions ; repeated	Carriageway : Plane off and resurfacing 40mm with some	£21,000
		patching in various stages of degradation ; alligator	channel re-profiling	
		cracking		

Funding