Appendix 2

* The schemes below were proposed as potential locations for consideration from a walkabout on 11 January 2012 between Village ward councillors and council's highways engineers.

Devolved Community Council Funded Schemes

Community Council: Dulwich – Village Ward Date: 13 January 2012

Candidate Road	Ward	Identified defects	Suggested treatment	Estimated Cost
Townley Road	Village	Carriageway: Areas have failing trench reinstatements and	Carriageway: Plane off and resurface	£18,000.00
(Outside No.27 - No.47)	\	some surface degradation	sections between Property No 27 to 47.	02,000,00
Townley Road	Village	Footway : Uneven footway with extensive trenching and patching; some cracking due to tree roots	Footway : Relay with flexible surfacing and roll over sections near proud tree roots	£3,000.00
(Outside No.73)	\		·	000 000 00
Townley Road (Outside No.105 –No 115)	Village	Footway: Uneven footway with extensive trenching and patching; some cracking due to tree roots	Footway: Relay with flexible surfacing and roll over sections near proud tree roots	£22,000.00
Townley Road	Village	Footway: Uneven footway with extensive trenching and	Footway: Relay with flexible surfacing and	£14,000.00
(Barclays to JW Woodyard	· ·	patching; some cracking due to tree roots	roll over sections near proud tree roots	
Lane)				
Townley Road	Village	Footway: Uneven footway with extensive trenching and	Footway: Relay with flexible surfacing and	£1,500.00
(Outside No.188)		patching; some cracking due to tree roots	roll over sections near proud tree roots	
Turney Road	Village	Footway: Uneven footway with extensive trenching and	Footway: Relay with flexible surfacing and	£2,000.00
(Outside No.87 – No.89)		patching; some cracking due to tree roots	roll over sections near proud tree roots	
Turney Road	Village	Footway: Uneven footway with extensive trenching and	Footway: Relay with flexible surfacing and	£2,000.00
(Outside No.140 – No.142)		patching; some cracking due to tree roots	roll over sections near proud tree roots	
Turney Road	Village	Footway: Uneven footway with extensive trenching and	Footway: Relay with flexible surfacing and	£2,000.00
(Outside No.63 – No.65)		patching; some cracking due to tree roots	roll over sections near proud tree roots	
Croxted Road	Village	Footway: Uneven footway with extensive trenching and	Footway: Relay with flexible surfacing and	£10,000.00
(Outside No. 224 to Bus Stop)	_	patching; some cracking due to tree roots	roll over sections near proud tree roots	
Croxted Road	Village	Footway: Uneven footway with extensive trenching and	Footway: Relay with flexible surfacing and	£5,000.00
(Outside No. 276 – No. 278)		patching; some cracking due to tree roots	roll over sections near proud tree roots	

Appendix 3 Devolved Community Council Funded Schemes

Update of Previous Schemes - 2011-12

Location	Description of Project	Ward	Allocation	Total Cost of Works	Balance Remaining	Started	Completed	Comments
Howletts Road	Carriageway Resurfacing	Village	£30,000.00	£5,426.24	£24,573.76	May-11	May-11	Completed - works undertaken under planned maintenance programme
Warmington Road	Carriageway Resurfacing	Village	£30,000.00	£23,649.52	£6,350.48	Sep-11	Sep-11	Completed
Potholes	Carriageway (Potholes)	Village	£3,000.00	£3,000.00	£0.00	various	various	completed
Bowen Drive	Carriageway Resurfacing	College	£45,000.00	£45,000.00	£0.00	Sep-11	Nov-11	completed