## Highway Candidate Schemes for Community Council funding 2010-11 Council Rotherhithe

Under spend from 2009-10 £60,138 2010 -11 allocation £100,000 Available for 2010 -11 £160,138

Candidate Scheme	Existing Situation		Proposed Work	Estimated
Candidate Scheme	Condition Report	Existing site photos	Proposed Work	Cost
<b>Lavender Road</b> (Surrey Docks Ward)	Carriageway : local subsidence,	72/10/00/10 10 122	Carriageway: full depth reconstruction in some locations, replacement of road marking	£60,000
Renforth Street (Surrey Docks Ward)	Footways: Untidy condition, important walking route, uneven Footway surface, existing trench subsidence trip hazards.		Footways: Repave to Council standard, reinstate cross overs,	£40,000

Green Hundred Rd (Livesy Ward)	Carriageway: Subsiding trench reinstatements, local subsidence, repeated patching in various stages of deterioration, aggregate stripping, longitudinal cracking, local transverse cracking, poor channel alignment,  Footways: Untidy condition, relatively low footfall, important walking route	20/07/2010 (3:01)	Carriageway: Full depth reconstruction in some locations, channel reprofiling, replacement of traffic calming measures, replacement of road marking Footways: Repave to Council standard, reinstate cross overs.	£60,000
Lower Rd (Osprey Est) (Rotherhithe Ward)	Footways: Untidy condition, important walking route, tree root lifting of paving, untidy tree pits.	72010/00/780 164000	Footways: Repave to Council standard, repave to departure from standard, improve tree pit, reinstate cross overs, defer work due to possibility of site redevelopment	£100,000
St Helena Road (Rotherhithe Ward)	Carriageway: Subsiding trench reinstatements, local subsidence, repeated patching in various stages of deterioration, aggregate stripping, rutting, longitudinal cracking, local transverse cracking, poor channel alignment, evidence of pot holes due to last cold spell, UKPMS condition rating Footways: Untidy condition, relatively low footfall, important walking route, tree root lifting of paving, untidy tree pits	8010/00/78 16:05	Carriageway: Resurfacing entire length full depth reconstruction in some locations, channel reprofiling, replacement of traffic calming measures, replacement of road marking  Footways: Repave to Council standard, repave to departure from standard, improve tree pit, reinstate cross overs, defer work due to possibility of site redevelopment	£100,000

Bush Road (Rotherhithe Ward)	Carriageway: Subsiding trench reinstatements, local subsidence, repeated patching in various stages of deterioration, aggregate stripping, rutting, longitudinal cracking, local transverse cracking, poor channel alignment, evidence of pot holes due to last cold spell, UKPMS condition rating =	2010.0
---------------------------------	--	--------

Carriageway: Resurfacing entire length of Bus lane, full depth reconstruction in some locations, channel reprofiling, replacement of traffic calming measures, replacement of road marking

£100,000

## Street Lighting Candidate Schemes for Community Council funding 2010-2011 Rotherhithe

 Under spend from 2009-10
 £37,000

 2010 -11 allocation
 £75,000

 Available for 2010 -11
 £112,000

Candidate Scheme	Existing Situation		Brancood Work	Estimated
Candidate Scheme	Condition Report	Existing site photos	Proposed Work	Cost
Admiral Place (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£2,000
Clifton Place (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£4,000
Gataker Street (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£4,000
Seth Street (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£4,000
Surrey Canal Road (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£4,000
Middleton Drive (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£6,000
Russia Dock Walk (Ward – Surrey Dock)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£6,000
Stalham Street (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to	£6,000

			current standards	
Cookham Crescent (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£8,000
Farrow Place (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£8,000
Hardy Close (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£8,000
Kinburn Street (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£8,000
Foundry Close (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£8,000
Gunwhale Close (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£8,000
Kenning Street (Ward - Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£8,000
Hyndman Street (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£10,000
Midship Close (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to	£10,000

			current standards	
Bray Crescent (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£10,000
Moodkee Street (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£10,000
Windrose Close (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£10,000
Hellbeck Close (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£12,000
Murdock Street (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£12,000
Galleon Close (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£12,000
Devonshire Grove (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£14,000
Acorn Walk (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£14,000
	50% or above of the existing lighting stock is			

Cranswick Road (Ward – Livesey)	structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£16,000
<b>Devon Street</b> (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£18,000
Sylvan Grove (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£18,000
Archangel Street (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£18,000
Canon Beck Road (Ward – Rotherhithe)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£22,000
Russia Dock Road (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£22,000
Ruby Triangle (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£22,000
<b>Delaford Road</b> (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£24,000
Barnards Wharf (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to	£24,000

			current standards	
Ruby Street (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£28,000
Nelson Walk (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£30,000
Sandgate Street (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£30,000
Bywater Place (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£32,000
Canada Street (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£32,000
Beatson Walk (Ward – Surrey Docks)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£50,000
Verny Road (Ward – Livesey)	50% or above of the existing lighting stock is structurally compromised.	To follow if selected	A new lighting scheme is required to replace structurally compromised lighting columns and bring the road up to current standards	£86,000