

Block/Address	Estate	Road	Post code
Burwash Hse	Kipling Est	Weston St	SE1 3RP
Simla Hse	Kipling Est	Weston St	SE1 3RP
Mardyke Hse	Mardyke Est	Townsend St	SE17 1HH
Helen Gladstone Hse	Nelson Sq Gdns	Nelson Sq	SE1 0QB
Redman Hse		Lant St., SE1	SE1 1JU
Styles Hse		The Cut, SE1	SE1 8DF
Prospect Hse	Gaywood Est	Gaywood St	SE1 6JY
Kennington Park House		Kennington Park Road	SE11 4JT
Laird Hse	Comber Est	Comber Grove	SE5 0LT
Crossmount Hse	Wyndham Est	Wyndham Rd	SE5 0XA
Otterburn Hse	Wyndham Est	Wyndham Rd	SE5 0XA
Tissington Court		Rotherithe New Road	
Addy Hse	Silwood Est	Rotherhithe New Rd	SE16 2PD
Brydale Hse	Silwood Est	Hawkestone Rd	SE16 2PU
John Kennedy Hse	Silwood Est	Rotherhithe Old Rd	SE16 2QF
Crane Hse	Pelican Est	Talfourd Place	SE15 5NF

Area Housing Office	Units	Floors	Cavity width	Access
	78	21	160mm	Flat roof
	79	21	160mm	Flat roof
Walworth	50	13	80mm	Flat roof
Boro & Bankside	47	12	70mm	Flat roof
Boro & Bankside	52	12	55mm	Flat roof
Boro & Bankside	48	12	80mm	Flat roof
Boro & Bankside	11	11	65mm	Flat roof
Walworth	40	11	70mm	Flat roof
Camberwell	82	20		Flat roof
Camberwell	82	20		Flat roof
Camberwell	81	20		Flat roof
Rotherhithe	62	16	TBC	Flat roof
Rotherhithe	48	16		Flat roof
Rotherhithe	48	16		Flat roof
Rotherhithe	48	16		Flat roof
Nunhd & Pckham	70	14	TBC	Flat roof

Survey comments	
Good access, clean and clear cavity	
Good access, clean and clear cavity	
Good access, clean and clear cavity	
Good access, clean and clear cavity	
Good access, clean and clear cavity	
Good access, clean and clear cavity	
Good cavity, clean and clear, Gable ends only	
Good access, clean and clear cavity	
1st floor to high to survey, Cherry picker to determine if cavity is sufficient to install	
1st floor to high to survey, Cherry picker to determine if cavity is sufficient to install	
1st floor to high to survey, Cherry picker to determine if cavity is sufficient to install	
1st floor to high to survey, Cherry picker to determine if cavity is sufficient to install	
Gable ends only, looks like cavity, will need cherry picker to survey further	
Gable ends only, looks like cavity, will need cherry picker to survey further	
Gable ends only, looks like cavity, will need cherry picker to survey further	
1st floor to high to survey, Cherry picker to determine if cavity is sufficient to install	

