

# LIVESEY RENOVATIONS


**BEFORE**




**AFTER**



Painting and units installed  
**2023**





# LIVESEY RENOVATIONS


**BEFORE**




**AFTER**



Painting and units installed  
**2023**





# LIVESEY RENOVATIONS


**BEFORE**




**AFTER**



Rear shutters  
**2023**





# LIVESEY RENOVATIONS


**BEFORE**




**AFTER**



Rear windows paint and repair  
**2023**






# LIVESEY RENOVATIONS


**BEFORE**

**AFTER**



Rear vents for HVAC finished off  
**2023**





# LIVESEY RENOVATIONS

**BEFORE**





**AFTER**



Rear guttering, deterioration and storm damage repair

**2023**





# LIVESEY RENOVATIONS

**BEFORE**





**AFTER**



HVAC vents finished to prevent water ingress

**2023**





# STUDENT/CSR


**PAINTING**

**ROLLERING**




Refreshing internal walls

**2023**







# STUDENT/CSR


**WEEDING**




**JETWASH**



Garden maintenance  
**2023**





# STUDENT/CSR

## BUILDING

## PAINTING



installing stairs and plaque making  
**2023**

